

September 22, 1980

Mr. James G. Keppler
Regional Director
Directorate of Regulatory Operations
Region III
U. S. Nuclear Regulatory Commission
Glen Ellyn, IL 60137

Reference: Zion Generating Station

Docket No. 50-295/DPR-39

Technical Specification, Section 6.6.2

Dear Mr. Keppler:

Enclosed please find Reportable Occurrence Report No. 50-295/80-40 for Zion Generating Station. This occurrence was found by internal audit on September 3, 1980.

This report is submitted to you in accordance with the requirements of the Technical Specifications, Section 6.6.2.b. (2), which states that conditions leading to operation in a degraded mode permitted by a limiting condition for operation or plant shutdown required by a limiting condition for operation requires a 30 day written report.

Very truly yours,

K. L. Graesser Superintendent Zion Station

Enclosure: Reportable Occurrence Report No. 50-295/80-40

1002/1