



**LOUISIANA
POWER & LIGHT**

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

October 1, 1980

D. L. ASWELL
Vice President-Power Production

LPL 15212
Q-3-A35.07.18

Mr. K. V. Seyfrit, Director, Region IV
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 18
"Flexible Liquid Tight Wiring Conduit Covering
Failure (Anaconda)"

REFERENCE: T. F. Gerrits conversation of September 30, 1980 with
Mr. R. C. Stewart

Dear Mr. Seyfrit:

As discussed with your Mr. R. C. Stewart on September 30, 1980, LP&L is continuing to evaluate the above subject. A report concerning this matter will now be submitted by October 17, 1980.

Yours very truly,

T. F. Gerrits for
D. L. Aswell

DLA:LLB:ncd

- cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
- 2) Director
Office of Management ✓
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Boo/
3
1/0

8010080 352

5