UPDATE REPORT - PREVIOUS REPORT DATE 8/2/80 NRC FORM 366 U. S. NUCLEAR REGULATORY COMMISSION (7.77) LICENSEE EVENT REPORT **EXHIBIT A** (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) 10 -10 10 0 0 0 - 10 10 3 4 11 11 1 0 57 CAT 54 CON'T 0 1 SOURCE L 60 5 0 0 0 3 6 8 0 0 711 3 7 9 8 0 9 2 9 8 0 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) [0] Review revealed that the Station Batteries' Surveillance Inspection [0]3] | required quarterly per T.S.4.8.2.3.2.b, was not performed on schedule. [0]4] | The test was originally scheduled for 5/22/79; however, it was performed! [0]5] Lon 6/27/79. The schedule deviation was discovered on 7/13/79. [0]6] Loccurrences involving surveillance schedule deviations were LER's [0]7] [50-368/79-049,79-041,78-024. Reportable per T.S.6.9.1.9.c CODE COMP. SUBCODE 0 9 SEQUENTIAL REPORT NO. OCCURRENCE REVISION CODE NO. COMPONENT HOURS (22) 101010101 M 23 IN 24 The surveillance was not conducted on schedule due to an oversight The importance of the surveillance program was discussed with the cognizant supervisor. Administration of the surveillance program has been centralized and is now controlled by the Planning & Scheduling Department 14 METHOD OF DISCOVERY DESCRIPTION (32) A (31) ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)] [Z] [3] [Z] [34] NA PERSONNEL EXPOSURES 80 PERSONNEL INJURIES DESCRIPTION (39) 80 NUMBER DESCRIPTION 41 NA

Chris N. Shively

an

NAC USE ONLY

501/968-2519

PHONE

9 11 12 LOSS OF OR DAMAGE TO FACILITY (3)

DESCRIPTION (45)

NAME OF PREPARER

PUBLICITY