



ARKANSAS POWER & LIGHT COMPANY  
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

September 25, 1980

1-090-24

Mr. K. V. Seyfrit, Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Comm.  
Reion IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011

SUBJECT: Arkansas Nuclear One - Unit 1  
Docket No. 50-313  
License No. DPR-51  
Licensee Event Report No. 80-031/03L-0  
File: 0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 1 Technical Specification b.12.3.2.b, attached is the subject report concerning excessive smoke coming from the turbocharger exhaust flange on the "B" Emergency Diesel Generator during a surveillance test.

Very truly yours,

*David C. Trimble*

David C. Trimble  
Manager, Licensing

DCT:GAC:lp

*808*

Attachment

cc: Mr. Victor Stello, Jr., Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Comm.  
Washington, D.C. 20555

Mr. Norman M. Haller, Director  
Office of Management and Program Analysis  
U. S. Nuclear Regulatory Comm.  
Washington, D.C. 20555

8013070617

*S*