



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA ST., N.W., SUITE 3100
ATLANTA, GEORGIA 30303

AUG 29 1980

Report No. 70-1151/80-20

Docket No. 70-1151 License No. SNM-1107 Safeguards Group III

Licensee: Westinghouse Electric Corporation
Nuclear Fuel Division
Columbia, SC 29205

Facility Name: Westinghouse Electric Corporation

Inspection at: Columbia, SC

Inspection conducted: July 21-25, 1980

Date of Last Material Control and Accounting Inspection Visit: 6/24-26/80

Inspector: J. W. Bates 8/29/80
J. W. Bates, Chemist Date

Approved by: F. P. Gillespie 8/29/80
for F. P. Gillespie, Chief, MC&A Section, Safeguards Branch Date

Inspection Summary

Areas Inspected: The Westinghouse measurement control program and followup on items of noncompliance.

The inspection involved 40 inspector-hours onsite by one NRC inspector and was begun during the regular hours.

Results: The licensee was found to be in compliance with NRC requirements in the two areas examined during the inspection except for the following two items:

1. Deficiency - Failure to make mixing/sampling test for two UNH storage tanks and the service tanks (80-20-01).
2. Deficiency - Failure to establish, maintain and follow, a system for the measurement of all SNM removed from inventory (80-20-02).

S-F2 80 - 108
Copy _____ of _____ Copies
18 Pages
This Document is not to be reproduced without specific approval of IE:II

80 108 10340