



AK Central file

UNITED STATES
ATOMIC ENERGY COMMISSION
DIRECTORATE OF REGULATORY OPERATIONS
REGION I
631 PARK AVENUE
KING OF PRUSSIA, PENNSYLVANIA 19406

10 MAY 1974

Yankee Atomic Electric Company
Attention: Mr. L. E. Minnick,
Vice President
20 Turnpike Road
Westboro, Massachusetts 01581

License No. DPR-5
Inspection No. 50-29/74-04

Gentlemen:

This refers to the inspection conducted by Mr. Oberg of this office on April 30-May 2, 1974 of activities authorized by AEC License No. DPR-5 and to the discussions of our findings held by Mr. Oberg with Mr. Audio and others of your staff at the conclusion of the inspection, and to a subsequent telephone discussion between Mr. Audio and Mr. Oberg on May 3, 1974.

Areas examined during this inspection are described in the Regulatory Operations Inspection Report which is enclosed with this letter. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Within the scope of this inspection, no violations or safety items were observed.

In accordance with Section 2.790 of the AEC's "Rules of Practice", Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the AEC's Public Document Room. If this report contains any information that you (or your contractor) believe to be proprietary, it is necessary that you make a written application within 30 days to this office to withhold such information from public disclosure. Any such application must include a full statement of the reasons on the basis of which it is claimed that the information is proprietary, and should be prepared so that proprietary information identified in the application is contained in a separate part of the document. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

05/07

DAVIS

BRUNNER

O'NEIL

ly

8011030 765

POOR ORIGINAL

Yankee Atomic Electric Company -2-

No reply to this letter is required; however, if you should have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

A. J. Brunner acting for

Eldon J. Brunner, Chief
Reactor Operations Branch

Enclosure:

RO Inspection Report No. 50-29/74-04

cc: Mr. H. Auto, Plant Superintendent
Star Route
Rowe, Massachusetts 01367

bcc:
RO Chief, ESLEB
RO:NQ (4)
DL (4)
RO Files
DR Central Files
RS
PDR
Local PDR
NSIC
DTIE
State of Massachusetts
Reg Reg Reading Room
OGC