APPENDIX A

NOTICE OF VIOLATION

Babcock and Wilcox Company Commercial Nuclear Fuel Plant

License No. SNM-1168

Based on the NRC inspection August 26-29, 1980, certain of your activities were apparently not conducted in full compliance with NRC requirements as indicated below. These items have been categorized as described in correspondence to you dated December 31, 1974.

As required by License Condition No. 9 authorizing use in accordance with the statements, representations and conditions contained in Section V, "Conditions" of the licensee's application; and subsection 7.4.3.1 "Area Moderation Control" that states "Service Water piping entering the pelletizing area shall be baffled or enclosed---so as to preclude spraying in the event of a joint or line rupture."

Contrary to the above, on August 26, 1980, one section of a sheet metal baffle was not in place over service water piping in the pelletizing area.

This is an infraction.