



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION IV  
811 RYAN PLAZA DRIVE, SUITE 1000  
ARLINGTON, TEXAS 76012

~~FD-405~~  
TERA

20 OCT 1980

Docket No. 99900505/80-02


Ebasco Services, Incorporated  
ATTN: Mr. B. E. Tenzer  
Vice President, Materials Engineering  
and Quality Assurance  
Two World Trade Center  
New York, NY 10048

Gentlemen:

Thank you for your letter of September 15, 1980, in response to our letter dated August 18, 1980, with an enclosure. We acknowledge that the deviation should have been more specific in referring only to the procedure entitled "Criteria and Procedures for the Evaluation of Support/Restraints."

We have no further questions regarding your response at this time. We will review your corrective and preventive actions during a future inspection.

Sincerely,

  
Uldis Potapovs, Chief  
Vendor Inspection Branch