Central felis

UNITED STATES ATOMIC ENERGY COMMISSION DIRECTORATE OF REGULATORY OPERATIONS REGION 631 PARK AVENUE

KING OF PRUSSIA, PENNSYLVANIA 19406

APR 1 7 1374

Yankee Atomic Electric Company Attention: Mr. L. E. Minnick Vice President

Licensa No. DPR-5 Inspection No. 50-29/74-02

20 Turnpike Road Westboro, Lassachusetts 01501

Contlemen:

This refers to the inspection conducted by Mr. Oberg of this office on March 11-15, 1974 at the Yan'tee Pacility in Nove, Massachusetts of activities authorized by ACC License No. DPR-5 and to the discussions of our findings held by 'r. Overg with lir. Autio and lir. Jones of your stiff at the conclusion of the inspaction, and to a subsequent telephone discussion between Mr. Autio and Mr. Oberg on April 1, 1974.

Areas examined during this inspection are described in the Regulatory Operations Inspection Report which is enclosed with this letter. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Our inspector also varified the steps you had taken to correct the violations brought to your attention in a letter dated October 19, 1973 following our last inspection. We have no further questions regarding these matters.

During this inspection, it was found that certain of your activities appeared to be in violation of ATC requirements. The items and references to the pertinent requirements are listed in the enclosure to this letter. This letter constitutes a notice sent to you pursuant to the provisions of Section 2.201 of the ALC's "Rules of Practice', Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office within 20 days of your receipt of this notice, a written statement of explanation in reply, including: (1) corrective steps which have been or will be taken by you, and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved.

o'Reilly Brunner Davis SUNNALLE L

8011050729

In accordance with Section 2.790 of the AEC's "Rules of Practice", Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the AEC's Public Document Room. If this report contains any information that you (or your contractor) believe to be proprietary, it is necessary that you make a written application within 20 days to this office to withhold such information from public disclosure. Any such application must include a full statement of the reasons on the basis of which it is claimed that the information is proprietary, and should be prepared so that proprietary information identified in the application is contained in a separate part of the document. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

an Lauri A. B. Davis, Acting for

E. J. Brunner, Chief Reactor Operations Branch

Enclosures:

1. Description of Violations

2. RO Inspection Report No. 50-29/74-02

cc: Mr. H. Autio, Plant Superintendent

bcc: RO Chief, FS&EB RO:HQ (4) DL (4) RO Files DR Central Files RS PDR Local PDR NSIC DTIE State of Massachusetts Reg Reg Reading Room OGC