

 **united engineers** & constructors inc.  
30 South 17th Street  
Post Office Box 8223  
Philadelphia, PA 19101

BOSTON  
ECHELON  
KNOXVILLE  
PHILADELPHIA

August 20, 1980


Mr. Uldis Potapovs, Chief  
Vendor Inspection Branch  
US Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011

Dear Mr. Potapovs:

Docket No. 9900510/80-01

We have revised our July 2, 1980 response to one of the deviations revealed during your inspection of May 5-9, 1980. A copy is attached for your subsequent follow up.

Sincerely,

  
R.A. Curnane, Vice President  
Product Support Operations

RAC/RHL/et  
attachment

A Raytheon Company

8011060 392

- B.2 Paragraph III.E of procedure GEDP-0013 (Preparation of Drawings) states in part that after a drawing is prepared, reviewed, comments incorporated and verified, "The drawing is then reviewed by the SDE (Supervising Discipline Engineer) and revised and/or approved and certified.

Contrary to the above, eight(8) of twenty-one(21) issued drawings examined were not certified.

With respect to Item B.2, Administrative Procedure AP-28 was revised during the inspection to only require certification of those drawings depicting ASME code items. All drawings depicting ASME Code items that were examined during the inspection were properly certified.

UE&C CORRECTIVE ACTION

The project will comply and certify, with stamped seal or signature and state registration number, all drawings as stated in GEDP-0013.

ACTION TAKEN TO PREVENT RECURRENCE

A memo has been issued to all disciplines clarifying the requirements for properly certifying drawings.

DATE OF CORRECTIVE ACTION COMPLETION

The backfit of certifying the tracings is scheduled to be complete by December 31, 1980. Copies will be reissued only when the drawing is revised.