

PDR



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION V
1990 N. CALIFORNIA BOULEVARD
SUITE 202, WALNUT CREEK PLAZA
WALNUT CREEK, CALIFORNIA 94596

001 16 1380

Docket No. 50-375

Rockwell International Corporation
8900 DeSoto Avenue
Canoga Park, California 91304

Attention: Dr. M. E. Remley, Manager
Health, Safety and Radiation Services

Gentlemen:

Subject: NRC Inspection of the L-85 Research Reactor Facility

This refers to the inspection conducted by Mr. J. R. Curtis of this office on September 24-25, 1980 of activities authorized by NRC License No. R-118 and to the discussion of our findings held by Mr. Curtis with you and other members of the staff at the conclusion of the inspection.

Areas examined during this inspection are described in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

No items of noncompliance with NRC requirements were identified within the scope of this inspection.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room. If this report contains any information that you believe to be proprietary, it is necessary that you submit a written application to this office, within 20 days of the date of this letter, requesting that such information be withheld from public disclosure. The application must include a full statement of the reasons why it is claimed that


8011060 800

OCT 18 1980

the information is proprietary. The application should be prepared so that any proprietary information identified is contained in an enclosure to the application, since the application without the enclosure will also be placed in the Public Document Room. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

Should you have any questions concerning this inspection, we will be glad to discuss them with you.

Sincerely,



H. E. Book, Chief
Fuel Facility and Materials
Safety Branch

Enclosure:
IE Inspection Report
No. 50-94780-01
375/80-03