Reseter Facilities

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION I

631 PARK AVENUE KING OF PRUSSIA, PENNSYLVANIA 19406

MAY 7 1978

Yankee Atomic Electric Company Attention: Mr. Robert H. Groce Licensing Engineer

License No. )PR-3 Inspection No. 76-06 Docket No. 50-29

20 Turnpike Road Westborough, Massachusetts 01581

Reference: Your letter dated April 12, 1976

In response to our letter dated March 15, 1976

Gentlemen:

Thank you for informing us of the corrective and preventive actions you documented in response to our correspondence. These actions will be examined during a subsequent inspection of your licensed program.

With respect to Item D of your letter, we understand that, based upon an April 28, 1976 telephone discussion between Mr. J. C. French of your staff and Mr. E. C. McCabe of this office, you will be placing boron and diesel fuel under the coverage of the Quality Assurance Program, and you will evaluate other materials for such coverage. If this understanding is incorrect, please notify us immediately.

The steps necessary to implement the above program will be examined during a subsequent inspection of your licensed facility.

Your cooperation with us is appreciated.

Sincerely,

Eldon J. Brunner, Chief Reactor Operations and Nuclear

Support Branch

a B Davis

cc: H. Autio, Plant Superintendent Donald G. Allen, President

bcc:
IE Mail & Files (For Appropriate Distribution)
PDR
Local PDR
NSIC
TIC
REG:I Reading Room
Region Directors (II, III, IV) (Report Only)
State of Massachusetts