

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION I
631 PARK AVENUE
KING OF PRUSSIA, PENNSYLVANIA 19406

MAR 15 1976

Yankee Atomic Electric Company
Attention: Mr. Robert H. Groce
Licensing Engineer
20 Turnpike Road
Westborough, Massachusetts 01581

License No. DPR-3
Inspection No. 76-06
Docket No. 50-29

Gentlemen:

This refers to the inspection conducted by Mr. J. Smith of this office on February 9-13, 1976 at your Yankee Atomic Electric Station in Rowe, Massachusetts and your offices in South Borough, Massachusetts of activities authorized by NRC License No. DPR-3 and to the discussions of our findings held by Mr. D. Haverkamp of this office with Mr. Autio and other members of your staff at the conclusion of the inspection, and to a subsequent telephone discussion between Mr. D. Haverkamp and Mr. Autio on February 18, 1976.

Areas examined during this inspection are described in the Office of Inspection and Enforcement Inspection Report which is enclosed with this letter. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Based on the results of this inspection, it appears that certain of your activities were not conducted in full compliance with NRC requirements, as set forth in the Notice of Violation, enclosed herewith as Appendix A. These items of noncompliance have been categorized into the levels as described in our correspondence to you dated December 31, 1974. This notice is sent to you pursuant to the provisions of Section 2.201 of the NRC's "Rules of Practice", Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office, within twenty (20) days of your receipt of this notice, a written statement or explanation in reply including: (1) corrective steps which have been taken by you and the results achieved; (2) corrective steps which will be taken to avoid further items of noncompliance; and (3) the date when full compliance will be achieved.

As indicated in Appendix A, we note that you have corrected Item B, and therefore you need not address this item in your response. We also note in Appendix A that the immediate corrective actions for Item A were completed; however, your response should detail the actions to prevent recurrence.




8011060 837

In accordance with Section 2.790 of the NRC's "Rules of Practice", Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosures will be placed in the NRC's Public Document Room. If this report contains any information that you (or your contractor) believe to be proprietary, it is necessary that you make a written application within 20 days to this office to withhold such information from public disclosure. Any such application must include a full statement of the reasons on the basis of which it is claimed that the information is proprietary, and should be prepared so that proprietary information identified in the application is contained in a separate part of the document. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,



Eldon J. Brunner, Chief
Reactor Operations and Nuclear
Support Branch

Enclosures:

1. Appendix A, Notice of Violations
2. Region I Inspection Report No. 50-29/76-06

cc: H. Autio, Plant Superintendent
Donald G. Allen, President

bcc:

IE Mail & Files (For Appropriate Distribution)
PDR
Local PDR
NSIC
TIC
REG:I Reading Room
Region Directors (II, III, IV) (Report Only)
State of Massachusetts