
Tel. 203/688-1911 Telex: 99297

Combustion Engineering, Inc. 1000 Prospect Hill Road Windsor, Connecticut 06095

DDH-80-069



September 30, 1980

U. S. Nuclear Regulatory Commission Region I 631 Park Avenue King of Prussia, Pennsylvania 19406

Attention: Mr. George H. Smith, Chief

Fuel Facility/Material Safety Branch

Reference: Letter from Mr. G. H. Smith to Mr. H. V.

Lichtenberger, dated September 4, 1980;

Combined Inspection 70-1100/80-05;30-03754/80-02.

Gentlemen:

This is in response to the above referenced letter in which you reported an infraction that was determined during your inspector's visit to our facility on July 9-11, 1980.

Appendix A to the referenced letter reported that a Radiological Control Committee had not been organized to perform functions as stated in item 14 of the application for byproduct material license 06-00217-06. As of this writing the Committee has been organized and intends to complete its annual audit function by October 31, 1980.

HU Luch fullinger

H. V. Lichtenberger

Vice President - Nuclear Fuel

Nuclear Power Systems - Manufacturing

HVL/PRR/kfg