2 3 SEP 1980



NUCLEAR REGULATORY COMMISSION REGION I

631 PARK AVENUE KING OF PRUSSIA, PENNSYLVANIA 19406

United Nuclear Corporation ATTN: Mr. C. E. Bowers

> General Manager UNC Recovery Systems

Wood River Junction, Rhode Island 02

02894

od River Junction, Knode Island

Gentlemen:

Subject: Inspection 70-820/80-15

This refers to the routine inspection conducted by Mr. P. Bissett of this office on August 27 and 28, 1980, of activities authorized by NRC License No. SNM-777 and to the discussions of our findings held by Mr. Bissett with Messrs. R. Gregg and J. L'Heureux of your staff at the conclusion of the inspection.

Areas examined during this inspection are described in the Office of Inspection and Enforcement Inspection Report which is enclosed with this letter. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Within the scope of this inspection, no items of noncompliance were observed.

In accordance with Section 2.790(d) of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, documentation of your control and accounting procedures for safeguarding special nuclear materials and your facility security measures for physical protection are deemed to be commercial or financial information within the meaning of 10 CFR 9.5(a)(4) and shall be subject to disclosure only in accordance with the provisions of 10 CFR 9.12; therefore, the enclosed inspection report will not be placed in the Public Document Room and will receive limited distribution.

No reply to this letter is required; however, should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

Walter G. Martin, Chief

Safeguards Branch

Enclosure: Office of Inspection and Enforcement Inspection Report Number 70-820/80-15

cc:

R. J. Gregg, Manager, Quality Assurance D. M. Schultz, Manager, Compliance