## U. S. NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT

## REGION I

Report No.	70-810/80-15	
Docket No.	70-820 License No. SNM-777 Safe	eguards Group1
Licensee:	United Nuclear Corporation	
	Wood River Junction, Rhode Island 02894	
Facility Na	ame: UNC Recovery Systems	
Inspection	At: Wood River Junction, Rhode Island	
Inspection	Conducted: August 27 and 28, 1980	
Date of Las	st Material Control and Accounting Inspection:	August 11-15, 1980
Type of Ins	pection: Unannounced Material Control and Accour	nting_
Inspectors:	P. H./Bissett, Auditor	9/15/80 date
	D. J. Helosly	9/15/80
	D. J. Holody, Mathematical Statistician	date
	90	date
Approved by	J. H. Joyner, Chief, Nuclear Material Contro Support Section, Safeguards Branch	9-18-80 date

Inspection Summary:

Area Inspected: Decommissioning Activities.

The inspection involved 20 inspector-hours onsite by two NRC inspectors and was begun during the regular hours.

Results: The licensee was found to be in compliance with NRC requirements in the area inspected.