SERVICES UNIT



October 30, 1980

1980 NOV 7 AM 10 22

L80-1840

FILE: RR 2 (NP-33-30-57)

Docket No. 50-346 License No. NPF-3 DISTAIDUTION SERVICES

Mr. James G. Keppler Regional Director, Region III Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Enclosed are three copies of Licensee Event Report 80-045 and supplemental information which has been revised. The revisions to the report are indicated by a "1" in the left margin of each page.

Please destroy your previous copies of this report and replace with the attached revision.

Yours truly,

Terry D. Murray

Station Superintendent

Terry Omunay

Davis-Besse Nuclear Power Station

TDM/1jk

Enclosure

cc: Mr. Victor Stello, Jr., Director Office of Inspection and Enforcement Encl: 30 copies

> Mr. Norman Haller, Director Office of Management Program Analysis Encl: 3 copies

Mr. Luis Reyes NRC Resident Inspector Encl: 1 copy

THE TOLEDO ESSON TOMPANY O EDISON PLAZA

300 MADISON AVENUE

TOLEDO, OHIO 43652