

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N E C P R 1 2 0 0 - 0 0 0 0 - 0 0 0 3 4 1 1 1 1 4 _____ 5
7 8 9 14 15 25 26 30 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

CON'T
0 1 R E P O R T S O U R C E L 6 0 5 0 0 0 2 9 9 7 0 9 0 8 8 0 8 1 0 0 1 1 8 0 9
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During routine plant inspection, an operator observed that 4160V breaker RHR 1D was
0 3 not capable of automatically closing; i.e. the closing spring was compressed (charg-
0 4 ed). Redundant systems were available. This event had no effects upon public health
0 5 or safety. R.T.S. 3.5.A.3

0 6 _____
0 7 _____
0 8 _____

0 9 C F 11 E 12 B 13 C K T B R K 14 E 15 Z 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20

17 L E R R O R E P O R T N U M B E R 8 0
18 E 19 H 20 Z 21 Z 22 0 0 0 0 23 N 24 0 25 A 26 G 0 8 0
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The General Electric Magna Blast 4160 VAC breaker for RHR pump 1D failed to charge
1 1 and made the pump inoperable. The latch monitoring switch did not close after break-
1 2 er tripped. The switch was replaced and the bracket for the spring release solenoid
1 3 was adjusted.

1 4 _____
1 5 E 28 1 0 0 29 NA 30 B 31 Operator Observation 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 6 Z 33 Z 34 NA 35 NA 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 7 0 0 0 37 Z 38 NA 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 8 0 0 0 40 L 41 NA 42
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 9 Z 47 NA 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

2 0 N 44 NA 45 8010210639 NRC USE ONLY
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NAME OF PREPARER L. F. Bednar

PHONE 402-825-3811