

EXXON NUCLEAR COMPANY, Inc.

RESEARCH AND TECHNOLOGY CENTER

2955 George Washington Way, Richland, Washington 99352

PHONE: (509) 375-7100

December 1, 1980

1000 DES 8
SERVICES
INTERNAL STOROS

ISNM 79020
1100 0901
Amend. No. 1

Mr. James B. Devine, Assistant Director
Export/Import and International Safeguards
Office of International Programs
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Reference: License No. ISNM 79020

Dear Mr. Devine:

Delays encountered at the reactor site have not permitted the return of material covered by the referenced import license within the initially perceived time frame. Consequently, please extend the expiration date of license ISNM 79020 from December 31, 1980 until December 31, 1981.

The material involved may be returned to the Exxon Nuclear Company, Inc. in Richland, Washington USA directly from the Oskarshamn I reactor or via Exxon Nuclear GmbH located in Lingen, West Germany.

If there are any questions with respect to this request or if additional information is needed please contact me on (509) 375-7288.

Sincerely,

Leo E. Hansen

Leo E. Hansen, Staff Specialist
Criticality Safety and Physical Security

LEH:slr

8012170

325

AN AFFILIATE OF EXXON CORPORATION