

Unit 3

LICENSEE EVENT REPORT

Report No. 3-80-28/1T

CONTROL BLOCK: _____ ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01	P	A	P	B	S	3	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5
LICENSEE CODE							LICENSE NUMBER										LICENSE TYPE					57	58			

01	L	6	0	5	0	-	0	2	7	8	7	1	2	0	3	8	0	8	1	2	1	7	8	0	9
REPORT SOURCE			DOCKET NUMBER								EVENT DATE						REPORT DATE								

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES ⑩

02 | During testing on December 1, 1980, the HPCI steam supply valve,

03 | MO-3-23-1L, failed to fully close. Subsequent stroking of the valve was

04 | successful. HPCI was taken out of service on December 3 for an inspec-

05 | tion of the valve and was returned to service on December 6. All other

06 | ECCS systems and the RCIC system were operable during the period of

07 | valve inoperability. Previous occurrence was LER 3-80-27/1T.

09	S	F	11	E	12	A	13	I	N	S	T	R	U	14	S	15	Z	16		
SYSTEM CODE			CAUSE CODE		CAUSE SUBCODE			COMPONENT CODE						COMP SUBCODE		VALVE SUBCODE				
17	8	0	-	0	2	8	/	0	1	T	-	0								
LER/RO REPORT NUMBER			EVENT YEAR		SEQUENTIAL REPORT NO.				OCCURRENCE CODE		REPORT TYPE		REVISION NO.							
18	Z	19	Z	20	Z	21	0	0	0	0	23	Y	24	A	25	L	2	0	0	26
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS			ATTACHMENT SUBMITTED		NPRO-4 FORM SUB		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER			

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS ⑰

10 | This event was caused by the HPCI system being inoperable for the valve

11 | inspection. After the valve failed to fully close during testing, it

12 | was disassembled, inspected, reassembled, and successfully tested.

5	E	28	1	0	0	29	N/A	30	B	31	Operator Observation	32	
FACILITY			POWER			OTHER STATUS			METHOD OF DISCOVERY				DISCOVERY DESCRIPTION
6	Z	33	Z	34	N/A	35	N/A	36	N/A	37	N/A	38	
RELEASE OF RELEASE			AMOUNT OF ACTIVITY				LOCATION OF RELEASE						
7	0	0	0	37	Z	38	N/A	39	N/A				
PERSONNEL EXPOSURES			DESCRIPTION										
8	0	0	0	40	N/A	41	N/A	42	N/A				
PERSONNEL INJURIES			DESCRIPTION										
9	Z	42	N/A	43	N/A	44	N/A	45	N/A				
LOSS OF OR DAMAGE TO FACILITY			DESCRIPTION										
0	N	44	N/A	45	N/A	46	N/A	47	N/A				
ISSUED			DESCRIPTION										

POOR ORIGINAL

801281323

NAME OF PREPARER PfWagait for M. J. Cooney

PHONE: (215) 841-5020