## 1750 Chestnut Street Tower II

January 6, 1981

POOR ORIGINAL

Mr. James P. O'Reilly, Director U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region II 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 - DOCKFT NO. 50-327 - FACILITY OPERATING LICENSE DPR-77 - REPORTABLE OCCURRENCE REPORT SORO-50-327/80193

The enclosed report provides details concerning the failure of a surveillance instruction to adequately demonstrate the operability of radiation monitoring channels providing automatic termination of release. This resulted in the plant entering action statements 30 and 31 of limiting condition for operation 3.3.3.9 and action statement 40 of limiting condition for operation 3.3.3.10 and is reportable under Sequeyah unit 1 Technical Specification 6.9.1.13.b.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

H. J. Green Director of Nuclear Power

Enclosure (3) cc (Enclosure):

Director (3)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, DC 20555

5

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington DC 20555

Mr. Bill Lavallee Nuclear Safety Analysis Center Palo Alto, California 94303

NRC Inspector, Sequoyah

No3/1