

YANKEE ATOMIC ELECTRIC COMPANY



20 Turnpike Road Westborough, Massachusetts 01581

TIC
Telephone 507 1301
JAN 8
B.4.1.1
WYR 80-132
SERVICES
MORNING

December 5, 1980

United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

POOR ORIGINAL

Attention: Mr. Boyce H. Grier, Director

- References:
- (a) License No. DPR-3 (Docket No. 50-29)
 - (b) USNRC Letter to YAEC dated I & E Bulletin No. 80-21

Dear Sir:

Subject: Response to IE Bulletin No. 80-21; "Valve Yokes Supplied by Malcolm Foundry Company, Inc."

The following information is provided in response to Reference (b).

As requested in Reference (b) a review of past purchase orders was conducted to determine if any valve parts were cast by the Malcum Foundry Company. The purchase orders had no information in this regard.

All active Safety Related valves required for safe shutdown or to mitigate an accident and made of carbon steel were visually inspected for cracking. No cracking was found, therefore, no further action is necessary.

The following information is submitted in response to your request for estimates of manpower expended in the review, preparation of reports and corrective actions required by this bulletin:

<u>Manpower Requirements</u>	<u>Hours</u>
Bulletin research and response	40
Corrective Actions	None Required

8101140953 Q


U. S. Nuclear Regulatory Commission
Attention: Mr. Boyce H. Grier, Director

December 5, 1980
Page 2

We trust that you find this information satisfactory; however, should you desire additional information please contact us.

Very truly yours,

YANKEE ATOMIC ELECTRIC COMPANY



D. E. Moody
Manager of Operations

BLD/sec

POOR ORIGINAL