

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower II

January 19, 1981

POOR ORIGINAL

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 3 - LOCKET
NO. 50-296 - FACILITY OPERATING LICENSE DPR-68 - REPORTABLE OCCURRENCE
REPORT BFRO-50-296/8016 REVISION 1

The enclosed report is a supplement to J. R. Calhoun's letter dated
June 11, 1980, concerning the cooling water flow being inadequate
upon completion of the flow test on 3D diesel generator heat exchanger.
This report is submitted in accordance with Browns Ferry unit 3
Technical Specification 6.7.2.b(2).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

H. J. Green
Director of Nuclear Power

Enclosure (3)

cc (Enclosure):

Director (3)

Office of Management Information and Program Control

U.S. Nuclear Regulatory Commission

Washington, DC 20555

Director (40)

Office of Inspection and Enforcement

U.S. Nuclear Regulatory Commission

Washington, DC 20555

Mr. Bill Lavalles

Nuclear Safety Analysis Center

Palo Alto, California 94303

Mr. R. F. Sullivan, NRC Inspector, Browns Ferry

App 2
S. 11