

Washington Public Power Supply System A JOINT OPERATING AGENCY

RICHLAND, WASHINGTON 99382

Nuclear Regulatory Commission Suite 202. Walnut Creek Plaza 1990 N. California Boulevard Walnut Creek, California 94596

December 12, 1980 GO-1-80-381

Attention:

Mr. G. S. Spencer

Chief Reactor Construction and Engineering Support Branch

WPPSS MUCLEAR PROJECTS NOS. 1/4

MRC INSPECTION - WNP-1/4

DATES OF INSPECTION - October 20-23, 1980

DOCKET MOS. 50-460 AND 50-513

CONSTRUCTION PERMIT NOS. CPPR-134 AND -174

Letter from G. S. Spencer to R. L. Ferguson, NRC Inspection

13 MP-1/4 Site, dated November 21, 1980.

The referenced correspondence delineated the results of the October 20-23, 1900 inspection of activities authorized by NRC Construction Permits Nos. CP/R-134 and -174. Further, the referenced correspondence identified certain activities which were not conducted in full compliance with PSAR requirements set forth in the Notice of Violation enclosed as Appendix A. This item of noncompliance has been categorized into a level as described in Supplement II of the Federal Register dated October 7, 1980 (45 FR 66754) as the Interim Enforcement Policy.

This letter is submitted in response to the referenced correspondence. The specific MRC finding, as identified, and the Supply System response is provided herewith as Appendix A.

D. W. Mazur

WNP-1/4 Program Director

Enclosure (1)

cc: _R Lewis - BPA

CR Bryant - BPA

V. Mani - UE&C. Phil.

V. Stello - Director of Inspection and Enforcement - NRC

APPENDIX A

Nuclear Regulatory Commission Region V Suite 262. Walnut Creek Plaza 1990 N. California Boulevard Walnut Creek. California 94596

POOR ORIGINAL

Docket No. 50-460 Construction Permit No. CPPR 134

NOTICE OF VIOLATION

As a result of the inspection conducted on October 20-23, 1980, and in accordance with the Interim Enforcement Policy, 45 FR 66754 (October 7, 1980), the following violation was identified:

10CFR50. Appendix B, Criterion IV, as implemented by Section 17.1.4 of the quality assurance program documented in the PSAR states, in part, that "Measures shall be established to assure that applicable regulatory requirements, design bases, and other requirements which are necessary to assure adequate quality are suitably included or referenced in the documents for procurement of material, equipment, and services, whether purchased by the applicant or by its contractors or supcontractor..."

Contrary to the above, as of October 23, 1980, the measures established by the site mechanical contractor and their painting subcontractor were not adequate to assure that procurement documents included those requirements necessary to assure adequate quality of the paint to be used on equipment within the containment. Contract specification No. 9779-211 requires the paint to have a decontamination factor of ten. The paint ordered, received and placed in storage for use had a decontamination factor of 6.3.

This is a severity level IV violation (Supplement II of Federal Register Notice 45 78 66754, dated October 7, 1980).

SUPPLY SYSTEM RESPONSE

Corrective Action Taken and the Results Achieved

The approval by the Architect Engineer contained in Corrective Waiver Request Numbers 211-039 and 257-048 permits the specified paint to have a decontamination factor of less than ten (10). Mobil Zinc 7 with a decontamination factor of 6.3 meets the requirements of ANSI N5.12 which specifies a typical range for decontamination factor of five to twenty (5 to 20). For clarification it should be noted that the test results for Mobil Zinc 7 (13F12) indicated an overall decontamination factor of 6.2 and not 6.3 as referenced in the Notice of Violation.

A system breakdown by the mechanical contractor and subcontractor respectively occurred as a result of a failure to specify the specific type and formula for Mobil Zinc 7 in the procurement documents and subsequent review of that document which resulted in the procurement, and actual receipt of the wrong formula Mobil Zinc 7 paint.

The mechanical contractor has documented this discrepancy in Nonconformance Report Number CNCR 211-232. Project Quality Assurance initiated Corrective Action Request Number 211-03 to the mechanical contractor for failure to adequately control sub-tier procurement.

Contract Maiver Request Numbers 211-039 and 257-048 have been reviewed by the Architect Engineers' Materials and Coatings Specialist and substantiated the prior approval of the aforementioned Contract Waiver Request.

Corrective Action to Preclude Recurrence

- 1). Project Quality Assurance personnel have been instructed as made all Contract Walver Requests dealing with material substitutions through the Quality Assurance Engineering Group of the Architect Engineer for approval. The Quality Assurance Engineering Group will provide the madessary interface with the Materials and Coatings Eggenalist to ensure proper review.
- 2). The dechanical contractor will review all existing and finance sub-ther procurement actions in accordance with extens required by Contract Walver Request Numbers 11-13 and 257-048 to ensure proper inclusion of all materials specification requirements.
- The contractor emphasis will be placed on contractor and subprocurement documents during the audit process course that applicable regulatory requirements, design and other requirements which are necessary to assure the substance quality are suitably included or issued in the successors for procurement of material, equipment, and sup-

Date of Foll Compliance

Monconformance aport Aumber CNCR 211-232, issued by the mechanical contractor establishes the control of the nonconforming paint as of this date.

POOR ORIGINAL

STATE OF WASHINGTON)

COUNTY OF BENTON)

D. M. MAZUR. Being first duly sworn, deposes and says: That he is the Program Director, WNP-1/4, for the WASHINGTON PUBLIC POWER SUPPLY SYSTEM, the applicant nerein; that he is authorized to submit the foregoing on behalf of said applicant; that he has read the foregoing and knows the contents thereor; and believes the same to be true to the best of his knowledge.

DATED 1-1- , 1980

therein ationed.

On this day personally appeared before me D. W. MAZUR to me known to be the individual who executed the foregoing instrument and acknowledged that he signed the same as his free act and deed for the uses and purposes

GIVEN under my hand and seal this 12th day of December, 1980

Hotary Public In and for the State of Washington Resilling at Boulon County