

POOR ORIGINAL

TENNESSEE VALLEY AUTHORITY
CHATTANOOGA, TENNESSEE 37402
1750 Chestnut Street Tower II

January 22, 1981

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 - DOCKET
NO. 50-327 - FACILITY OPERATING LICENSE DFB-77 - REPORTABLE OCCURRENCE
REPORT SQRC-50-327/80292

The enclosed report provides details concerning the freezing of sense
lines for the main feedwater flow, steam flow, and steam pressure instrument
channels. This event is reported in accordance with Sequoyah unit 1
Technical Specification 6.9.1.13.b.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

H. J. Green
Director of Nuclear Power

Enclosure (3)

cc (Enclosure):

Director (3)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Mr. Bill Levallee
Nuclear Safety Analysis Center
Palo Alto, California 94303

NRC Inspector, Sequoyah

A002
S
//

S 8102020386