



UNITED STATES  
NUCLEAR REGULATORY COMMISSION

REGION II  
101 MARIETTA ST., N.W., SUITE 3100  
ATLANTA, GEORGIA 30303

JAN 29 1981



Alabama Power Company  
ATTN: R. P. McDonald  
Vice President-Nuclear Generation  
P. O. Box 2641  
Birmingham, AL 35291

Gentlemen:

Subject: Report Nos. 50-348/80-37 and 50-364/80-51

This refers to the routine inspection conducted by B. R. Crowley of this office on December 15-18, 1980, of activities authorized by NRC License No. NPF-2 and Construction Permit No. CPPR-86 for the Farley facility, and to the discussion of our findings held with G. Hairston at the conclusion of the inspection.

Areas examined during the inspection and our findings are discussed in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Within the scope of this inspection, no violations or deviations were disclosed.

We have examined actions you have taken with regard to previously identified enforcement matters. These are discussed in the enclosed inspection report.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room. If this report contains any information that you (or your contractor) believe to be proprietary, it is necessary that you make a written application within 20 days to this office to withhold such information from public disclosure. Any such application must include a full statement of the reasons on the basis of which it is claimed that the information is proprietary, and should be prepared so that proprietary information identified in the application is contained in a separate part of the document. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,

C. E. Murphy, Chief  
Reactor Construction and Engineering  
Support Branch

Enclosure: (See Page 2)

8103050390

Q

JAN 29 1981

Enclosure:

Inspection Report Nos. 50-348/80-37  
and 50-364/80-51

cc w/encl:

W. O. Whitt, Executive Vice President  
F. L. Clayton, Jr., Senior Vice President  
H. O. Thrash, Manager-Nuclear Generation  
O. D. Kingsley, Jr., Manager, Nuclear Engineering  
and Technical Services  
J. W. McGowan, Manager-Operations  
Quality Assurance  
W. G. Hairston, III, Plant Manager  
W. C. Petty, Manager-Quality Assurance  
(Design and Construction)  
R. E. Hollands, Jr., QA Supervisor