

TIC

THE CINCINNATI GAS & ELECTRIC COMPANY



E. A. BORGMANN
SENIOR VICE PRESIDENT

September 2, 1980

United States
Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Attention: Mr. James G. Keppler,
Regional Director

RE: WM. H. ZIMMER NUCLEAR POWER STATION
UNIT 1 - IE BULLETIN 80-19 and REV. 1
FAILURE OF MERCURY WETTED RELAYS IN
RPS SYSTEMS, DOCKET #50-358, W.O. 57300,
JOB E-5590, ITEM #956, IE BULLETIN FILE

Gentlemen:

Mercury wetted relays are not utilized in the Reactor Protection System at the Wm. H. Zimmer Nuclear Power Station - Unit 1. IE Bulletin 80-19 is therefore not applicable to this facility and no further response is required.

With regards to the question raised in your cover letter of July 31, 1980, please be advised that between ourselves and our supplier we expended approximately four manhours to investigate the status of mercury wetted relays on the Zimmer facility.

Very truly yours,

THE CINCINNATI GAS & ELECTRIC COMPANY

By 
E. A. Borgmann

WPC:mjl

cc: NRC Office of Inspection and Enforcement

R. F. Scheibel
R. E. Cotta
C. W. Beringhaus
H. C. Brinkmann
W. W. Schwiers
B. K. Culver
J. R. Schott
J. D. Flynn
F. T. Daniels
W. D. Waymire (Pink)

SEP 5 1980

8009170 422

SEP 5 1980