## POWER AUTHORITY OF THE STATE OF NEW YORK

10 COLUMBUS CIRCLE

NEW YORK, N. Y. 10019

GEORGE T BERRY PRESIDENT & CHIEF OPERATING OFFICER

JOSEPH R. SCHMIEDER

ENG NEER

PRESIDENT & CHIEF

LERGY W SINCLAIR
SENIOR VICE PRESIDENT
B CHIEF FINANCIAL
OFFICER

THOMAS R FREY SENIOR VICE PRESIDENT & GENERAL COUNSEL

EXECUTIVE VICE PRESIDENT & DIRECTOR OF POWER OPERATIONS

JOHN W. BOSTON

(212) 397-6200

TRUSTEES

JOHN 5 DYSON

GEORGE L. INGALLS

RICHARD M. FLYNN

ROBERT I MILLONZI

FREDERICK R. CLARK



December 5, 1980 JPN-80-56

Director of Nuclear Peactor Regulation U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Attention: Mr. Thomas A. Ippolito, Chief

Operating Reactors Branch No. 2

Division of Licensing

Subject: James A. FitzPatrick Nuclear Power Plant

Docket No. 50-333

Inservice Inspection Summary Report

Dear Sir:

This submittal consist of 5 copies of the James A. FitzPatrick Inservice Inspection Summary Report for the Spring/Summer 1980 outage. The report contains two major items of work: 1) the results of the component, weld and pipe support examinations conducted in accordance with the James A. Fitz-Patrick Inservice Inspection Program, and 2) the results of the inservice inspection of the reactor pressure vessel internals, core spray sparger, and jet pump beams.

All results are acceptable in accordance with the ASME Code, Section XI. The report has been reviewed by Authority personnel and the authorized inspector from Hartford Steam Boiler Inspection and Insurance Company. The approval of both plant management and the authorized inspector is shown on the NIS-1 data form.

Very truly yours,

J., P. Bayne

Senior Vice President Nuclear Generation

20 2 TO E FILE

80121002244

Q