

Brunswick Steam Electric Plant  
P. O. Box 10429  
Southport, NC 28461

February 26, 1981

FILE: B09-13510  
SERIAL: BSEP/81-0459

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, GA 30303



BRUNSWICK STEAM ELECTRIC PLANT, UNIT NOS. 1 & 2  
LICENSE NOS. DPR-71 AND DPR-62  
DOCKET NOS. 50-325 AND 50-324  
ANNUAL REPORT IN ACCORDANCE WITH 10CFR50.59

Dear Mr. O'Reilly:

In accordance with 10CFR50.59, the enclosed changes in procedures and changes in the facility as described in the safety analysis report and Special Test Procedures not contained in the safety analysis report, are submitted. During the period of 1980, no testing/experiments were conducted which were not described in the safety analysis report.

This report fulfills the requirement for annually submitting a report containing a brief description of such changes, tests, and experiments including a summary of the safety evaluation of each.

This report also fulfills the requirement to report annually the challenges and failures of safety relief valves during the past year.

Very truly yours,

A handwritten signature in dark ink, appearing to read "C. R. Dietz".

C. R. Dietz, General Manager  
Brunswick Steam Electric Plant

RMP/mew

Enclosure

cc: Mr. B. J. Furr  
Mr. V. Stello

R 8103250 286