



EDISON PLAZA
300 MADISON AVENUE
TOLEDO, OHIO 43652

March 6, 1980

L80-189

FILE: RR 2 (NP-32-79-14)

Docket No. 50-346
License No. NPF-3

Mr. James G. Keppler
Regional Director, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Enclosed are three copies of Licensee Event Report 79-130 and the supplemental information sheet, which have been revised. The revisions to the report are indicated by a "1" in the left margin.

Please destroy your previous copies of this Licensee Event Report and replace with the attached revision.

Yours truly,

Terry D. Murray
Station Superintendent
Davis-Besse Nuclear Power Station

TDM/ljk

Enclosure

cc: Mr. Victor Stello, Jr., Director
Office of Inspection and Enforcement
Encl: 40 copies LER 79-130 Rev. 1

Mr. Norman Haller, Director
Office of Management Program Analysis
Encl: 3 copies LER 79-130 Rev. 1

8008110 559 5