

LICENSEE EVENT REPORT

CONTROL BLOCK (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

P A B V S 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 1 9
LICENSEE CODE 14 15 LICENSE NUMBER 16 17 LICENSE TYPE 30 31 CAT 58CONT
REPORT SOURCE L 6 0 5 0 0 0 3 3 4 0 0 1 3 1 8 0 0 0 3 0 4 8 0 9
60 61 DOCKET NUMBER 62 63 EVENT DATE 64 65 REPORT DATE 66

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

At 1315 hours on 1/30/80, the refueling team was advised that all prerequisites were met and core alterations could start. At 1330 hours, the inservice Boric Acid Transfer Pump [CH-P-2B] tripped on thermal overload. Core alterations were stopped at this time. Core alteration was resumed at 1400 hours after verifying the pump recirculation pressure was above the required technical specification value. No degradation to any margins of safety either to the plant or the public resulted.

SYSTEM CODE R B 11 CAUSE CODE X 12 CAUSE SUBCODE Z 13 COMPONENT CODE Z Z Z Z Z Z Z 14 COMP SUBCODE Z 15 VALVE SUBCODE Z 16
LER NO. REPORT NUMBER 17 8 0 21 22 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED N 20 NPD-4 FORM SUB N 24 PRIME COMP SUPPLIER Z 25 REVISION NO. 0 32 COMPONENT MANUFACTURER Z 9 9 9 9 26
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB PRIME COMP SUPPLIER COMPONENT MANUFACTURER
E 18 Z 19 Z 20 Z 21 0 0 0 0 N 20 N 24 Z 25 Z 9 9 9 9 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

The cause was not definitely determined. Numerous blender operations due to faulty blender controls shifted [CH-P-2B] the Boric Acid Transfer pumps from slow to fast speed and back numerous times. Blender operation was suspended and makeup to [CH-TK-1B] Boric Acid Tank was stopped. Blender controls [FCV-CH-119A] were repaired on 2/2/80, thus precluding any further problems.

FACILITY STATUS H 28 % POWER 0 0 0 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY Z 31 DISCOVERY DESCRIPTION Operator observation 32
ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 37 Z 38 N/A 39

PERSONNEL INJURIES NUMBER DESCRIPTION 40 N/A 41

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 42 N/A 43

PUBLICITY ISSUED DESCRIPTION 44 N/A 45

NAME OF PREPARER J. A. Werling

PHONE 412-643-1258

POOR ORIGINAL

NRC USE ONLY