NSP

## NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 58401

August 14, 1980

Mr. James G. Keppler Director, Region III Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

Dear Mr. Keppler:

PRAIRIE ISLAND NUCLEAR GENERATING PLANT

Docket Nos. 50-282 and 50-306

In response to IE Bulletin No. 80-19, no relays of the type described are in use in reactor protection systems at this facility.

Yours truly,

D. E. Gilberts Vice President

Power Production

cc: Mr. G. Charnoff
Director, U. S. Nuclear Regulatory Commission
Division of Reactor Operations Inspection
Office of Inspection and Enforcement
Washington, D. C. 20555

DEG:nk

AUG 1 8 1980