YANKEE ATOMIC ELECTRIC COMPANY



Rowe, Massachusetts 01367 August 13, 1976

Mr. J. P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region 1
631 Park Avenue
King of Prussia, Pennsylvania 19406

Subject: Reportable Occurrence 50-29/76-08/01T

Rod Ejection Accident Analysis Error

Dear Mr. O'Reilly:

In accordance with Technical Specifications, Section E.2.a, the attached licensee Event Report is hereby submitted.

Very truly yours,

This I Lacrent for HA Autic

Herbert A. Autio Plant Superintendent

JLS/jb

Enclosure

cc: (40) Director, Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, D. C. 20555

(3) Director, Office of Management Information & Program Control U.S. Nuclear Regulatory Commission Washington, D. C. 20555

8278