

NUCLEAR REGULATORY COMMISSION

REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

OCT 6 1980

N

Docket No. 50-373 Docket No. 50-374

Commonwealth Edison Company ATTN: Mr. Cordell Reed Vice President Post Office Box 767 Chicago, IL 60690



This refers to the special inspection conducted by Mr. I. T. Yin of this office on August 29, and September 2-5 and 10, 1980, of activities at La Salle County Station, Units 1 and 2, authorized by NRC Construction Permits No. CPPR-99 and No. CPPR-100 and to the discussion of our findings with you and your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

Based on our recently conducted inspections of the corrective actions you have taken, we are satisfied that the provisions in our letter of August 14, 1980, have been satisfactorily completed. Your staff was informed of this on September 5, 1980. We understand that Unit 2 small bore pipe hanger and restraint installation activities will not be resumed until you have notified us of your evaluation of the effectiveness of the additional controls you placed in effect due to the problems encountered on Unit 1.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room, except as follows. If this report contains information that you or your contractors believe to be proprietary, you must apply in writing to this office, within twenty days of your receipt of this letter, to withhold such information from public disclosure. The application must include a full statement of the reasons for which the information is considered proprietary, and should be prepared so that proprietary information identified in the application is contained in an enclosure to the application.



- 2 -

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

James G. Keppler Director

Enclosure: IE Inspection Reports No. 50-373/80-40 and No. 50-374/80-26

cc w/encl: Mr. J. S. Abel, Director of Nuclear Licensing Mr. L. J. Burke, Site Construction Superintendent Mr. T. E. Quaka, Quality Assurance Supervisor Mr. R. H. Holyoak, Station Superintendent Mr. B. B. Stephenson, Project Manager Central Files Reproduction Unit NRC 20b AEOD Resident Inspector, RIII PDR Local PDR NSIC TIC Mr. Dean Hansell, Office of Assistant Attorney General

RIII Win/np Danielson

Neglet

Weisler Williams RIII

Spessard Hershman 9 RIII

Fiorelli

Norelius

RIII Keppler