

POOR ORIGINAL

PHILADELPHIA ELECTRIC COMPANY

RECEIVED DISTRIBUTION SERVICES UNIT

2301 MARKET STREET

P.O. BOX 8699

1960 NOV 24 PM 12 42

PHILADELPHIA, PA. 19101

(215) 841-4000

US NRC
DISTRIBUTION SERVICES
BRANCH

November 10, 1980

Mr. Boyce H. Grier, Director
Region I
Office of Inspection & Enforcement
US Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406


SUBJECT: Report of Plant Startup Following Fourth Refueling
Outage, March 1980 -- Peach Bottom Atomic Power Station
Unit No. 2, Docket No. 50-277

Dear Mr. Grier:

Enclosed are two copies of the Plant Startup Report following
the Fourth Refueling Outage for Peach Bottom Atomic Power Station Unit
No. 2, March, 1980.

This report is being submitted in compliance with the Technical
Specifications of Operating License DPR-44.

Very truly yours,



W. M. Alden
Engineer-In-Charge
Nuclear Section
Generation Division

Enclosures

cc: Director
Office of Inspection & Enforcement
US Nuclear Regulatory Commission
Washington, DC 20555 (25 copies)

Mr. Norman Haller, Director
Office of Management & Program
Analysis
US Nuclear Regulatory Commission
Washington, DC 20555 (2 copies)

8011250308

P

A027
5
1/20