

LPR

40-3453


Atlas Minerals

Division of Atlas Corporation

1400 East Evans Avenue, Suite 401

Denver, Colorado 80222

Phone (303) 757-1759

Gordon T. Swanby
Vice President

November 4, 1980



Mr. John J. Linehan
Uranium Recovery Licensing Branch
Division of Waste Management
United States Nuclear Regulatory Commission
Washington, DC 20555

Dear Mr. Linehan:

Confirming my discussion with Mr. Garcia on November 3 concerning radiation readings near the Texas Tour Center, I verbally gave him the enclosed information.

With regard to the question of quality assurance procedures, we will be sending you a separate letter on this subject.

Sincerely,

Gordon T. Swanby

GTS:rf

Enc.

cc: Peter Garcia
Wayne Jensen
Dale Edwards

U.S. NRC
DISTRIBUTION SERVICES
BRANCH

1980 NOV 19 AM 10 45

U.S. NRC
DISTRIBUTION
SERVICES UNIT

8012080

385

17844

Copy to NRC.

MONTH September 1980

	<u>U-NAT</u>	<u>Pb-210</u>	<u>RN-222</u>
MPC	5×10^{-12} uci/ml	4×10^{-12} uci/ml	30×10^{-10} uci/ml
Location			
#1	$.022 \times 10^{-12}$ uci/ml		3.3×10^{-10} uci/ml
#2	$.038 \times 10^{-12}$ uci/ml		4.5×10^{-10} uci/ml
#3	$.038 \times 10^{-12}$ uci/ml		4.2×10^{-10} uci/ml
#4	$.014 \times 10^{-12}$ uci/ml		1.3×10^{-10} uci/ml
#5	$.006 \times 10^{-12}$ uci/ml		2.0×10^{-10} uci/ml

July 80

#1 0.034×10^{-12} uci/ml

$2.0 \pm 0.11 \times 10^{-10}$ uci/ml

Aug 80

#1 0.014×10^{-12} uci/ml

$4.9 \pm 0.13 \times 10^{-10}$ uci/ml

Cont. Airs
(3rd qtr.)

Pa 226

#1 - $.0012 \times 10^{-12}$ uci/ml

#2 - $.0023 \times 10^{-12}$ uci/ml

#3 - $.0021 \times 10^{-12}$ uci/ml

#4 - $.0004 \times 10^{-12}$ uci/ml

#5 - $.00047 \times 10^{-12}$ uci/ml

Th 230

#1 - $.14 \times 10^{-14}$ uci/ml

#2 - $.46 \times 10^{-14}$ uci/ml

#3 - $.28 \times 10^{-14}$ uci/ml

#4 - $.15 \times 10^{-14}$ uci/ml

#5 - $.14 \times 10^{-14}$ uci/ml