



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION V  
1990 N. CALIFORNIA BOULEVARD  
SUITE 202, WALNUT CREEK PLAZA  
WALNUT CREEK, CALIFORNIA 94596

December 19, 1980



Docket Nos. 50-460 and 50-513

Washington Public Power Supply System  
P. O. Box 968  
Richland, Washington 99352

Attention: D. W. Mazur  
WNP 1/4 Program Director

Gentlemen:

Subject: NRC Inspection of Washington Nuclear Projects 1 and 4

This refers to the inspections conducted by Messrs. R. C. Haynes, D. F. Kirsch and P. P. Narbut of this office during the period between November 17 to December 5, 1980 of activities authorized by NRC Construction Permit Nos. CPPR-134 and CPPR-174, and to the discussion of our findings held with you and other members of your staff on November 20 and December 5, 1980.

Areas examined during this inspection are described in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Based on the results of this inspection, it appears that certain of your activities were not conducted in full compliance with NRC requirements, as set forth in the Notice of Violation, enclosed herewith as Appendix A. These items of noncompliance have been categorized into a level as described in the Federal Register on October 7, 1980 (45 RF 66754) as the Interim Enforcement Policy.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room. If this report contains any information that you believe to be proprietary, it is necessary that you submit a written application to this office, within 20 days of the date of this letter, requesting that such information be withheld from public disclosure. The application

8102180056

must include a full statement of the reasons why it is claimed that the information is proprietary. The application should be prepared so that any proprietary information identified is contained in an enclosure to the application, since the application without the enclosure will also be placed in the Public Document Room. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

Should you have any questions concerning this inspection, we will be glad to discuss them with you.

Sincerely,



G. S. Spencer, Chief  
Reactor Construction and  
Engineering Support Branch

Enclosures:

- A. Appendix A - Notice of Violation
- B. IE Inspection Report  
Nos. 50-460/80-15  
50-513/80-15

cc w/enclosures:

M. E. Witherspoon, Division Manager  
Quality Assurance, WPPSS