



Carolina Power & Light Company

Brunswick Steam Electric Plant
P. O. Box 10429
Southport, NC 28461

March 31, 1981

FILE: B09-13514
SERIAL: BSEP/81-0677

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II, Suite 3100
101 Marietta Street
Atlanta, GA 30303

BRUNSWICK STEAM ELECTRIC PLANT, UNIT NOS. 1 & 2
LICENSE NOS. DPR-71 AND DPR-62
DOCKET NOS. 50-325 AND 50-324
SUPPLEMENTAL RESPONSE TO NOTICE OF VIOLATION

Dear Mr. O'Reilly:

In our response to IE Inspection Report 50-325/80-42 and 50-324/80-39 dated February 3, 1981, a commitment date of April 1, 1981, was established to perform procedural changes to correct Violation E, Items 3 and 4. Since this response was issued, the QA organization has been completely reorganized as described in the meeting held on March 13, 1981, in the Region II offices with your staff. Due to this complete reorganization, the need to develop or revise a vast number of procedures, including those noted in the violation, has been identified to ensure that they reflect the new corporate QA manual. The rewriting of these procedures, including those noted in the violation, is currently in progress.

Based on this reorganization and the additional identified work load, the procedures requiring development or revision identified in Violation E will not be complete until June 1, 1981.

Very truly yours,

C. R. Dietz, General Manager
Brunswick Steam Electric Plant

RMP/jro

cc: Mr. R. A. Hartfield
Mr. V. Stello, Jr.

8104220 886