



Wisconsin Electric POWER COMPANY
231 W. MICHIGAN, P.O. BOX 2046, MILWAUKEE, WI 53201

October 6, 1980

Mr. J. G. Keppler, Regional Director
Office of Inspection and Enforcement,
Region III
U. S. NUCLEAR REGULATORY COMMISSION
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

DOCKET NOS. 50-266 AND 50-301
LICENSEE EVENT REPORT NO. 80-011/03L
POINT BEACH NUCLEAR PLANT UNITS 1 AND 2

Enclosed is Licensee Event Report No. 80-011/03L
(a 30-day report) with attachment which provides a description
of an event reportable according to Technical Specification
15.6.9.2.B.3, "Observed inadequacies in the implementation of
administrative or procedural controls which threaten to cause
reduction of degree of redundancy provided in reactor protection
systems or engineered safety feature systems".

Very truly yours,

C. W. Fay, Director
Nuclear Power Department

Enclosure

Copy to NRC Resident Inspector

8010150 379

AC62
S
111
OCT 10 1980