Regulatory Docket File

YANKEE ATOMIC ELECTRIC COMPANY



Rowe, Massachusetts 01367 January 13, 1977



Mr. J. P. O'Reilly, Director U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region 1 631 Park Avenue King of Prussia, Pennsylvania 19406

Subject: Reportable Occurrence 50-29/76-14/03L

Number 1 High Pressure Safety Injection Pump's Seal Failure

Dear Mr. O'Reilly:

In accordance with Technical Specifications, Section E.2.b.2, the attached Licensee Event Report is hereby submitted.

Very truly yours,

Herbert A. Autio Plant Superintendent

Herbert a. auto

JLS/jb

Enclosure:

- cc: (40) Director, Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, D. C. 20555
 - (3) Director, Office of Management Information & Program Control U.S. Nuclear Regulatory Commission Washington, D. C. 20555

565