
Cheif ALOD



NJK-81-97

March 2, 1981

J. Keppler, Regional Director Office of Inspection and Enforcement Region III U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137



Reference: Quad-Cities Nuclear Power Station Docket Number 50-265, DPR-30, Unit Two Appendix A, Table 3.1-3 and Section 6.6.B.1.e.

Enclosed please find Reportable Occurrence Report Number RO 81-4/01T for Quad-Cities Nuclear Power Station. This occurrence was previously reported to Region III, Office of Inspection and Enforcement by telephone on February 23, 1981, and by telecopy on February 23, 1981.

This report is submitted to you in accordance with the requirements of Technical Specification 6.6.B.l.e. as a malfunction of one or more components which prevents or could prevent, by itself the fulfillment of the functional requirements of system(s) used to cope with accidents analyzed in the SAR.

Very truly yours,

COMMONWEALTH EDISON COMPANY QUAD-CITIES NUCLEAR POWER STATION

N. J. Kalivianakis Station Superintendent

NJK: JRW/bb

Enclosure

cc R. F. Janecek N. Chrissotimos