



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION I
631 PARK AVENUE
KING OF PRUSSIA, PENNSYLVANIA 19406

5 FEB 1981

Docket No. 50-317
50-318

Baltimore Gas and Electric Company
ATTN: Mr. V. R. Evans
Vice President, General Services
P. O. Box 1475
Baltimore, Maryland 21203



Gentlemen:

Subject: Combined Inspection Nos. 50-317/80-20 and 50-318/80-24

This refers to the routine inspection conducted by Mr. W. Madden of this office on December 7-11, 1980, at Calvert Cliffs Nuclear Power Plant, Lusby, Maryland, of activities authorized by NRC License Nos. DPR-53 and DPR-69 and to the discussions of our findings held by Mr. Madden with Mr. L. B. Russell of your staff at the conclusion of the inspection, and to subsequent telephone discussions between Mr. Mathews and Mr. Madden on December 16, 1980, January 23 and January 27, 1981.

Areas examined during this inspection are described in the Office of Inspection and Enforcement Inspection Report which is enclosed with this letter. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Our inspector also verified the steps you have taken to correct the items of noncompliance brought to your attention in a letter dated August 19, 1980. We have no further questions regarding your action at this time.

Within the scope of this inspection, no items of noncompliance were observed.

In accordance with Section 2.790(d) of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, documentation of findings of your control and accounting procedures for safeguarding special nuclear materials and your facility security measures for physical protection are deemed to be commercial or financial information within the meaning of 10 CFR 9.5(a)(4) and shall be subject to disclosure only in accordance with the provisions of 10 CFR 9.12; therefore, the enclosed inspection report will not be placed in the Public Document Room and will receive limited distribution.


8104030788

Q

5 FEB 1981

No reply to this letter is required; however, should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,



Walter G. Martin, Chief
Safeguards Branch

Enclosure:

Combined Office of Inspection and Enforcement Inspection
Report Nos. 50-317/80-20 and 50-318/80-24 (Contains
2.790 Information)

cc:

R. M. Douglas, Manager, Quality Assurance (w report cover sheet only)
L. B. Russell, Plant Superintendent (w cy of encl)
T. Sydnor, General Supervisor, Operations QA (w report cover sheet only)
R. C. L. Olson, Principal Engineer (w report cover sheet only)
J. A. Tiernan, Manager, Nuclear Power (w report cover sheet only)
C. Steinhagen, General Supervisor, Security Services (w cy of encl)
A. E. Lundvall, Jr., Vice President (w report cover sheet only)