



Northern States Power Company

414 Nicollet Mall Minneapolis, Minnesota 55401 Telephone (612) 330-5500

May 15, 1981

Mr J G Keppler
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137



PRAIRIE ISLAND NUCLEAR GENERATING PLANT Docket No. 50-306 License No. DPR-60

Missed Surveillance Test

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

This event is reported in compliance with Technical Specification 6.7.B.2(C) since it represents an inadequacy in the implementation of administrative or procedural controls.

L O Mayer, PE

Manager of Nuclear Support Services

LOM/TMP/bd

cc: Director, IE, USNRC (30)
Director, MIPC, USNRC (3)
NRC Resident Inspector
MPCA

Attn: J W Ferman

-over-