

APPENDIX A
NOTICE OF VIOLATION

Haverford Community Hospital
Havertown, Pennsylvania 19083
License No. 37-13464-02

Docket No. 30-13669

As a result of the inspection conducted on March 26, 1981, and in accordance with the Interim Enforcement Policy, 45 FR 66754 (October 7, 1980), the following violation was identified:

Condition 15 of your license requires that you possess and use licensed material in accordance with the statements, representations, and procedures contained in an application dated December 7, 1977, and a letter dated June 6, 1978.

Item 3 of your letter dated June 6, 1978, requires that you perform a linearity check of your dose calibrator using a precalibrated source of technetium-99m monthly.

Contrary to this requirement, as of March 26, 1981, you failed to make the required linearity check monthly. It was noted that you performed a linearity test monthly but it was not the test of instrument linearity as described in the "Guide for the Preparation of Applications for Medical Programs" in that you did not measure activity over a 48 hour period.

This is a Severity Level V Violation (Supplement VII).

Pursuant to the provisions of 10 CFR 2.201, Haverford Community Hospital is hereby required to submit to this office within twenty-five days of the date of this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Under the authority of Section 182 of the Atomic Energy Act of 1954 as amended this response shall be submitted under oath or affirmation.

Dated 20 APR 1981

Laurence F. Friedman
for John D. Kinneman, Chief, Materials
Radiological Protection Section
Technical Inspection Branch