



Wisconsin Electric POWER COMPANY

231 WEST MICHIGAN, MILWAUKEE, WISCONSIN 53201

December 23, 1980

Mr. James Keppler, Regional Director
Office of Inspection and Enforcement,
Region III
U. S. NUCLEAR REGULATORY COMMISSION
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

DOCKET NO. 50-266
POINT BEACH NUCLEAR PLANT
LICENSEE EVENT REPORT NO. 80-015/01T-0

Enclosed is Licensee Event Report No. 80-015/01T-0
(a 14-day follow-up report) and an attachment which provides a
description of an event reportable in accordance with Technical
Specification 15.6.9.2.A.9, "Performance of structures, systems,
or components that requires remedial action or corrective measures
to prevent operation in a manner less conservative than that
assumed in the accident analyses in the safety analysis report or
Technical Specifications bases."

Very truly yours,

C. W. Fay, Director
Nuclear Power Department

Enclosure

Copy to NRC Resident Inspector

8101120

333

5
Hooz
S.I.
JAN 0 5 1981