



Commonwealth Edison
Zion Generating Station
Shiloh Blvd. & Lake Michigan
Zion, Illinois 60099
Telephone 312/746-2084

December 31, 1980

Mr. James G. Keppler
Regional Director
Directorate of Regulatory Operations
Region III
U. S. Nuclear Regulatory Commission
Glen Ellyn, Illinois 60137

Reference: Zion Generating Station
Docket No. 50-295/DPR-39
Technical Specification, Section 6.6.2

Dear Mr. Keppler:

Enclosed please find updated Reportable Occurrence Report No. 50-295/80-51 for Zion Generating Station. The original was submitted December 15, 1980.

This report is submitted to you in accordance with the requirements of the Technical Specifications, Section 6.6.2.b.(2), which states that conditions leading to operation in a degraded mode permitted by a limiting condition for operation require a 30-day written report.

Very truly yours,

K. L. Graesser
Superintendent
Zion Station

cc: J. Kohler/J. Waters

Enclosure: Updated Reportable Occurrence
Report No. 50-295/80-51

Handwritten: A002
5/1

8101120

338

Handwritten: 5 JAN 05 1981