



ARKANSAS POWER & LIGHT COMPANY
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

January 8, 1981

1981 JAN 12 PM 3 41
MIDDLE SOUTH UTILITIES SYSTEM
COMMUNICATIONS UNIT

1-011-06

Mr. K. V. Seyfrit, Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Comm.
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

SUBJECT: Arkansas Nuclear One - Unit 1
Docket No. DPR-51
Licensee Event Report No. 80-039/03L-1
(File: 0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 1 Technical Specification 6.12.3.2.b, attached is the subject report concerning the failure of the exhaust fan (VEF-37A) to the Hydrogen purge system. This is a revision to a previous report submitted November 25, 1980.

Very truly yours,

David C. Trimble
Manager, Licensing

DCT:GAC:lp

SDJ

Attachment

cc: Mr. Victor Stello, Jr., Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Comm.
Washington, D.C. 20555

Mr. Norman M. Haller, Director
Office of Management and Program Analysis
U. S. Nuclear Regulatory Comm.
Washington, D.C. 20555

5

810 1180 543