

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION III 799 ROOSEVELT ROAD GLEN ELLYN, ILLINOIS 60137

April 28, 1981

Docket No. 50-341

The Detroit Edison Company ATTN: Mr. Donald A. Wells Manager, Quality Assurance 2000 Second Avenue Detroit, MI 48226



Gentlemen:

This refers to the routine safety inspection conducted by Messrs. B. H. Little and P. M. Byron of this office on February 16 - March 31, 1981, of activities at Enrico Fermi, Unit 2, authorized by NRC Construction Permit No. CPPR-87 and to the discussion of our findings with Mr. W. Fahrner at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room, except as follows. If this report contains information that you or your contractors believe to be proprietary, you must apply in writing to this office, within twenty-five days of the date of this letter, to withhold such information from public disclosure. The application must include a full statement of the reasons for which the information is considered proprietary, and should be prepared so that proprietary information identified in the application is contained in an enclosure to the application.

R. F. Heishman, Acting Director Division of Resident and Project Inspection

Enclosure: IE Inspection Report No. 50-341/81-03

cc w/encl:
Central Files
Reproduction Unit NRC 20b
AEOD
Resident Inspector, RIII
PDR
Local PDR
NSIC
TIC
Ronald Callen Michigan
Public Service Commission
Eugene B. Thomas, Jr.,
Attorney