

# MOORE MUNICIPAL HOSPITAL

1500 SOUTHEAST FOURTH STREET - BOX 6949 - MOORE, OKLAHOMA 73153 - (405) 794-7721

BOBBY G. THOMPSON, Administrator

April 6, 1981

Karl V. Seyfrit, Director  
Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive, Suite 1000,  
Arlington, Texas 76011

RE: License No. 35-17213-01

Dear Mr. Seyfrit,

In reply to your letter dated March 13, 1981, we have instituted the following actions to correct our deficiencies:

- 1a) The dose calibrator is now being tested daily with documentation for consistency, monthly for linearity, and efforts are now being put forth to locate Molybdenum-99 for annual testing. Cesium-137 for accuracy will be done within a month for the annual check required. I might add, testing has been performed during the period September 1, 1977, to February 9, 1981, but record keeping has been poor and total requirements were not met.
- 1b) The Radioisotope Committee will meet quarterly as required by license and will become more aware of its responsibility to the quality of Nuclear Medicine performed at our institution.
- 2) All byproduct materials were tested before disposal, but inadequate records were kept which have begun as of this date.
- 3) All posting requirements have been corrected.
- 4) Copies of monitoring reports on all required personnel are enclosed in this report and will be submitted as required in the future.


In order that we not encounter difficulties of this nature in the future and to insure that our patients and personnel are protected, and the quality of care rendered be proper, we have employed a Radiological Technician who has as part of her responsibility, the directing of Nuclear Medicine. The Radioisotope Committee will also be more closely monitoring the activities of this department to assure all things are being done properly.

8106030192

This will also give this Committee more responsibility and need to meet. We will be reapplying for a license in September of this year and will be closely evaluating the requirements of our license. We also are employing a Consultant who will assist us on our license re-application and will be explaining to me management responsibility.

If any further information is required, please notify.

Sincerely,




Bobby G. Thompson,  
Administrator

CC: J. Leon Gregston, M.D.  
Chief Nuclear Medicine Department

Bill Nance, Chief Radiology Tech.

In compliance with your letter dated May 10, 1981, we are notarizing the above information as presented.



Signed before me this 13<sup>th</sup> day of May, 1981.



NOTARY PUBLIC

My Commission Expires January 26, 1985