

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

October 20, 1980
JUL 23 AM : 41

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNIT 1 - NRC-OIE LETTER RII:DLA 50-327/80-34 -
INSPECTION REPORT - RESPONSE TO DEFICIENCY

The subject deficiency dated September 26, 1980, cited TVA with one
deficiency in accordance with 10 CFR 2.201. Enclosed is our response.

If you have any questions, please get in touch with D. L. Lambert at
FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L M Mills
L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Director (Enclosure)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

6011210 078

OFFICIAL COPY

ENCLOSURE

SEQUOYAH NUCLEAR PLANT UNIT 1
RESPONSE TO DEFICIENCY 50-327/80-34-07

Deficiency

As required by Technical Specification 6.8.1.d, written procedures shall be established, implemented and maintained for the Plant Physical Security Plan. Physical Security Plan Implementing Procedure PHYSI-13 requires, in part, annual requalification for individuals assigned to the fire brigade. PHYSI-13 further requires that the Safety Section verify the training records of employees assigned to the fire brigade.

Contrary to the above, on August 15, 18, and 19, 1980, two individuals were assigned to the fire brigade who had not received requalification training since January 1979.

Corrective Steps Which Have Been Taken and Results Achieved

When this item was identified, the two operators who had not received the requalification training were immediately removed from all fire brigade duties. Both men have since received the required requalification training and are now certified for assignment to fire brigade duties.

Corrective Steps Which Will Be Taken to Avoid Further Noncompliance

Operations Section Instruction Letter No. 82 contains a list of all employees who are subject to be assigned fire brigade duties. Each person designated to assign employees to fire brigade duties has been instructed to verify that each person selected for this duty has met current qualifications. The plant safety engineering supervisor reviews and maintains a copy of this list and schedules training to ensure timely requalification of all employees listed.

No further corrective action is planned for this item.

Date When Full Compliance Will Be Achieved

The deficiency has been corrected and we are now in compliance.